


# POWR-GARD® Fuse Datasheet

## KLQ SERIES (10x35mm) FUSES

### Temperature Rerating Curve (Temperature of Air Immediately Surrounding Fuse)



**Operating**  
Temperature: -55° C to +125° C

**Storage**  
Temperature: -20° C to +60° C  
at relative humidity 75%

### Time Current Curves

